

Main Bus Entry, spalled concrete, recoating



Close up on damage area






Area to be recoated at the bus entrance area







Repairs at Lane 15





Recoating at the exit of Lane 21



Repair at the main exit door





Repairs at the exit door



Trench drain shoulders







