

SCHEDULE "A" FORM

CUSTOMER: DTA-TRANSIT CENTER EAST DATE: 10/9/23

PAGE# 1 OF 5

JOB LOCATION: DULUTH, MN

INSPECTED BY: JIM D

PANEL

TYPE	MANUF	MODEL #	LOCATION	TESTED	V-READING
	<u>EDWARDS</u>			<u>JD</u>	

PLEASE LIST ANY COMMENTS CONCERNING ANY AND ALL TESTING:

FIRE DEFICIENCIES

SMOKE DETECTORS THAT FAILED:

MICHIGAN ST DOUBLE DOORS AND BIKE PATROL ROOM

PULL STATIONS THAT FAILED:

MICHIGAN ST DOUBLE DOORS AND EQUIPMENT ROOM OUTSIDE ELEVATORS

SYSTEM INFORMATION

SMOKE DETECTORS NOT TESTED:

ELEVATOR OUTSIDE JANITOR CLOSET

